

Instructions: **Bold** fields must be completed.

Station Summary			
Waterbody Name UNNAMED		Waterbody ID Code 294700	Sample ID (YYYYMMDD-CY-FD) 20161013-69-02
Sampling Location US Grunster Rd		Database Key 133649563	
SWIMS Station ID 10043173		SWIMS Station Name UNNAMED TRIB TO N BR OF PIGEON RIVER US GRUNSTERN RD	
Latitude 44.6632882	Longitude -88.9536229	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) WOLF RIVER		Watershed Name PIGEON RIVER	County WAUPACA

Sample and Site Descriptors	
Sample Collector (Last Name, First) DAVID BOLHA	Project Name UPPER PIGEON RIVER WATERSHED ASSESSMENT - EAST_2

Sampling Device

Kick Net Surber Sampler Eckman
 Ponar Artificial Substrate Hess Sampler Other: _____

Habitat Sampled

Riffle Run Pool
 Other Shoreline Composite Proportionally-Sampled Habitat
 Littoral Zone Profundal Zone Wetland

Total Sampling Time (min) 4	Estimated Area Sampled (m ²) 2	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>1</u>
--------------------------------	---	-------------------------------------	------------------------------------

Reason For Sampling

Least Impacted Reference Baseline Impact / Treatment Site
 Control Site Trend Other: _____

Water Temp. (°C) 8.1°C 46.5	D.O. (mg/l) 8.25	D.O. (% sat.) 69.1	pH (su) 7.38	Conductivity (umhos/cm) 522.9	Transparency (cm) 120
---	---------------------	-----------------------	-----------------	----------------------------------	--------------------------

Water Color

Clear Turbid Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s) Moderate (0.15 m/s - 0.5 m/s) Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) .2	Average Stream Width of reach (m) 2
---	---	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): _____ Gravel (ladybug to tennisball): 20
 Sand: 50 Clay: _____ Silt/Muck: 20 Overhanging Vegetation: 10
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 90 Canopy Cover at Sample Site (%) 0

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Watershed	Factors that may be influencing Water Resource Integrity	Local	Watershed
Biological			Chemical		
Algae: - Diatoms / Periphyton	N	N	Chlorine	N	N
- Filamentous Algae	N	N	Dissolved Oxygen	PL	PL
- Planktonic Algae	N	N	Nutrients (P, N...)	PL	PL
Iron Bacteria	N	N	Toxics: - Inorganic (Metals)	N	N
Macrophytes	N	N	- Organic (PCBs, pesticides...)	N	N
Slimes	N	N	Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion	PL	PL
			Point Source - Specify:	N	N
Physical			Pasturing of Livestock	N	N
Bank Erosion	PL	PL	Runoff: - Barnyard	N	N
Channelization: - Upstream	N	N	- Construction	N	N
- Downstream	N	N	- Cropland	PL	PL
Hydraulic Scour / Channel Incision	N	N	- Urban	N	N
Impoundment: - Upstream	PH	PH	Septic Systems	N	N
- Downstream	N	N	Tile Drainage - Organic Soils	N	N
Low Flow	PL	PL	- Mineral Soils	N	N
Sedimentation	PH	PH	Springs	N	N
Sludge	N	N	Tributary(s)	N	N
Thermal	PL	PL	Wetland	N	N
Turbidity	N	N	Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter Andrew Krollmann	Taxonomist Dimick Jeffrey	Estimated Percent of Sample Sorted 20%
Date Processed 4/3/17	Specimens Saved Subsample archived in ABL until Sept 2020	

E2-61
 C3-98
 D2-139

