

Instructions: **Bold** fields must be completed.

Station Summary			
Waterbody Name BOWER CREEK		Waterbody ID Code 118400	Sample ID (YYYYMMDD-CY-FD) 20161010-05-03
Sampling Location		Database Key 133902247	
SWIMS Station ID 10040706		SWIMS Station Name BOWER CREEK 315M DS CTH GV	
Latitude 44.450172	Longitude -87.99822	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) LOWER FOX		Watershed Name EAST RIVER	County BROWN

Sample and Site Descriptors	
Sample Collector (Last Name, First) ANDREW HUDAK	Project Name EAST RIVER- AOC MONITORING - EAST_1_CMP16

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 6	Estimated Area Sampled (m ²) 10	Number of Samples in Composite 1	Replicate No. 1 of 1
---------------------------------------	---	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 11.5	D.O. (mg/l) 7.1	D.O. (%sat.) 64.9	pH (su) 7.6	Conductivity (umhos/cm) 1.059	Transparency (cm) 34
--------------------------------	---------------------------	-----------------------------	-----------------------	---	--------------------------------

Water Color <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.21	Average Stream Width of reach (m) 8
---	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): **30** Rubble (tennisball to basketball): **10** Gravel (ladybug to tennisball): _____
 Sand: _____ Clay: _____ Silt/Muck: **30** Overhanging Vegetation: **10**
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: **20** Other (_____): _____
 Embeddedness of Substrate at Sample Site (%) **70** Canopy Cover at Sample Site (%) **70**

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
Physical				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Bonnie Richards</i>	Taxonomist <i>Derrick Jeffrey</i>	Estimated Percent of Sample Sorted <i>27</i>
Date Processed <i>10-26-16</i>	Specimens Saved <i>Subsample archived in ABL until Jan 2020</i>	

*C2: 29 A2: 23 B3: 15
 D3: 58
 (135)*