

Instructions: Bold fields must be completed.

Station Summary		
Waterbody Name EAST TWIN RIVER	Waterbody ID Code 84000	Sample ID (YYYYMMDD-CY-FD) 20171010-31-04
Sampling Location		Database Key 149675608

SWIMS Station ID 10008206	SWIMS Station Name EAST TWIN RIVER - EAST TWIN RIVER - TOWNLINE ROAD		
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	
Basin (WMU) TWIN - DOOR - KEWAUNEE			County KEWAUNEE
Watershed Name EAST TWIN RIVER		Datum Used if using GPS WGS84 or NAD83	

Sample and Site Descriptors	
Sample Collector (Last Name, First) MARY GANSBERG	Project Name EAST TWIN RIVER TWA 2017

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 2.2	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: TWA

Water Temp. (C) 11.0	D.O. (mg/l) 9.5	D.O. (% sat.) 85.1	pH (su) 7.8	Conductivity (umhos/cm) 803	Transparency (cm)
--------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	--------------------------

Water Color	Estimated Stream Velocity (m/s)
<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	<input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.8	Average Stream Width of reach (m) 7.6
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 20 Gravel (ladybug to tennisball): 70
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 10
Canopy Cover at Sample Site (%) 80

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Watershed	Factors that may be influencing Water Resource Integrity		Local	Watershed
Biological			Chemical				
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Taylor Hasz</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>13%</i>
Date Processed <i>10-23-17</i>	Specimens Saved <i>Subsample archived in ABL until Dec 2020</i>	

*C2 69
 A3 92*

161

