


DURING

Field 1
Fabric
Leach
and
Skid
Loader



Tuesday, August 16, 2016 11:16:19 AM - IMG_20160705_142238112_HDR[1]

DURING

Field 2
Excavation




DURING

Field 2
Fabric liner




DURING

Field 2
Leach complete
No foundation gravel



AFTER

Field 1
complete



Tuesday, August 16, 2016 11:20:58 AM - IMG_20160816_111835906[1]

AFTER



Field 2
complete

Tuesday, August 16, 2016 11:20:30 AM - IMG_20160816_111817949[1]