

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name UNNAMED		Waterbody ID Code 121000	Sample ID (YYYYMMDD-CY-FD) #20171012-05-06
Sampling Location			Database Key 149643492
SWIMS Station ID 10049253		SWIMS Station Name UNT TO EAST RIVER 40M US MILL RD	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) LOWER FOX		Watershed Name EAST RIVER	County BROWN

Sample and Site Descriptors	
Sample Collector (Last Name, First) ANDREW HUDAK	Project Name UPPER EAST RIVER TWA 2017

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 3	Estimated Area Sampled (m ²) 3	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>1</u>
--------------------------------	---	-------------------------------------	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 12.49	D.O. (mg/l) 6.1	D.O. (%sat.) 57.9	pH (su) 8.19	Conductivity (umhos/cm) 1034	Transparency (cm) 712a
--------------------------	--------------------	----------------------	-----------------	---------------------------------	---------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.15	Average Stream Width of reach (m) 2.0
---	---	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 60 Gravel (ladybug to tennisball): 20
 Sand: 10 Clay: _____ Silt/Muck: 10 Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 10
 Canopy Cover at Sample Site (%) 0

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Channelization: - Upstream				Runoff: - Barnyard			
- Downstream				- Construction			
Hydraulic Scour / Channel Incision				- Cropland			
Impoundment: - Upstream				- Urban			
- Downstream				Septic Systems			
Low Flow				Tile Drainage - Organic Soils			
Sedimentation				- Mineral Soils			
Sludge				Springs			
Thermal				Tributary(s)			
Turbidity				Wetland			
Other - Specify:				Other - Specify:			

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Justin Kawalski</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>70%</i>
Date Processed <i>3/2/18</i>	Specimens Saved <i>Subsample archived in ABL until May 2021</i>	

E3
136

