

Instructions: **Bold** fields must be completed.

Station Summary

Waterbody Name UNNAMED	Waterbody ID Code 836550	Sample ID (YYYYMMDD-CY-FD) 20171010-14-03
----------------------------------	------------------------------------	---

Sampling Location Culvert at GH CD	Database Key 151307072
--	----------------------------------

SWIMS Station ID 10010079	SWIMS Station Name TRIB TO BEAVER CREEK - CD XING
-------------------------------------	---

Latitude 43.50392	Longitude 89.00261	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS WGS84 or NAD83
-----------------------------	------------------------------	--	--

Basin (WMU) UPPER ROCK	Watershed Name BEAVER DAM RIVER	County DODGE
----------------------------------	---	------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) MICHAEL SORGE	Project Name BEAVER CREEK TWA 2017
---	--

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 14.1	D.O. (mg/l) 5.60	D.O. (% sat.) 54.7	pH (su) 7.65	Conductivity (umhos/cm) 735	Transparency (cm)
--------------------------------	----------------------------	------------------------------	------------------------	---------------------------------------	--------------------------

Water Color <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
--	--	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): 10 Rubble (tennisball to basketball): 40 Gravel (ladybug to tennisball): 20
 Sand: 15 Clay: _____ Silt/Muck: 15 Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 30 **Canopy Cover at Sample Site (%)** 100 (Culvert)

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Justin Kowalski</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>70%</i>
Date Processed <i>4/11/18</i>	Specimens Saved <i>Subsample archived in ABZ label Jun 2021</i>	

B1
 202

