

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name UNNAMED		Waterbody ID Code 5011982	Sample ID (YYYYMMDD-CY-FD) 20171115-17-02
Sampling Location Under bridge		Database Key 151068293	
SWIMS Station ID 10048593		SWIMS Station Name UNNAMED TRIB TO IRVING CREEK AT HWY K	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) LOWER CHIPPEWA		Watershed Name WILSON CREEK	County DUNN

Sample and Site Descriptors	
Sample Collector (Last Name, First) MYCAL RALEIGH	Project Name WEST DISTRICT NC STREAM STRATIFIED SITES 2017

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) .5 min	Estimated Area Sampled (m ²) 1 m ²	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>1</u>
-------------------------------------	--	-------------------------------------	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: NCSR

Water Temp. (C)	D.O. (mg/l)	D.O. (% sat.)	pH (su)	Conductivity (umhos/cm)	Transparency (cm)
-----------------	-------------	---------------	---------	-------------------------	-------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 1	Average Stream Width of reach (m) 1 m
---	--	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): 90 Rubble (tennisball to basketball): 5 Gravel (ladybug to tennisball): _____
 Sand: 5 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____
 Embeddedness of Substrate at Sample Site (%) 40 Canopy Cover at Sample Site (%) 100 (6-10)

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water-shed	Factors that may be influencing Water Resource Integrity	Local	Water-shed
Biological			Chemical		
Algae: - Diatoms / Periphyton	N	U	Chlorine	U	U
- Filamentous Algae	N	U	Dissolved Oxygen	U	U
- Planktonic Algae	N	U	Nutrients (P, N...)	U	U
Iron Bacteria	N	U	Toxics: - Inorganic (Metals)	U	U
Macrophytes	N	U	- Organic (PCBs, pesticides...)	U	U
Slimes	N	U	Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion	N	U
Physical			Point Source - Specify:		
Bank Erosion	N	U	Pasturing of Livestock	N	U
Channelization: - Upstream	N	U	Runoff: - Barnyard	N	U
- Downstream	N	U	- Construction	N	U
Hydraulic Scour / Channel Incision	N	U	- Cropland	PL	U
Impoundment: - Upstream	N	U	- Urban	U	U
- Downstream	N	U	Septic Systems	U	U
Low Flow	U	U	Tile Drainage - Organic Soils	U	U
Sedimentation	PH	U	- Mineral Soils	U	U
Sludge	N	U	Springs	U	U
Thermal	U	U	Tributary(s)	U	U
Turbidity	N	U	Wetland	U	U
Other - Specify:			Other - Specify:		

Comments From survey in summer, stream substrate is all sand/silt, only boulder/mud is under bridge. Croplands around site, but pretty good buffers. Stream is in a small valley-type terrain.

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Karla Wilcox</i>	Taxonomist <i>Dimick Jeffrey</i>	Estimated Percent of Sample Sorted <i>130%</i>
Date Processed <i>8/16/18</i>	Specimens Saved <i>Subsample archived in ABL until Dec 2021</i>	

A1 = 51
 C3 = 78 129

