

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name CASCO CREEK	Waterbody ID Code 91600	Sample ID (YYYYMMDD-CY-FD) 20180921-31-10
Sampling Location		Database Key 168775434

SWIMS Station ID 10020875	SWIMS Station Name CASCO CREEK-50 FEET ABOVE BRIDGE OFF CREVICE ROAD.
-------------------------------------	---

Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
-----------------	------------------	---	--

Basin (WMU) TWIN - DOOR - KEWAUNEE	Watershed Name KEWAUNEE RIVER	County KEWAUNEE
--	---	---------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) MARY GANSBERG	Project Name NE LAKESHORE TMDL SUPPLEMENTAL MONITORING
---	--

Sampling Device

D-Frame Kick Net Surber Sampler Eckman
 Ponar Artificial Substrate Hess Sampler Other: _____

Habitat Sampled

Riffle Run Pool
 Other Shoreline Composite Proportionally-Sampled Habitat
 Littoral Zone Profundal Zone Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 0.4	Number of Samples in Composite	Replicate No. _____ of _____
---------------------------------------	--	---------------------------------------	-------------------------------------

Reason for Sampling

Least Impacted Reference Baseline Impact / Treatment Site
 Control Site Trend Other: TMDL

Water Temp. (C) 17.6	D.O. (mg/l) 7.9	D.O. (% sat.) 83.4	pH (su) 8.1	Conductivity (umhos/cm) 800	Transparency (cm)
--------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	--------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.2	Average Stream Width of reach (m) 5
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 40 Gravel (ladybug to tennisball): 50
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 0 **Canopy Cover at Sample Site (%)** 40

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter Logan Cutler	Taxonomist Dimick Jeffrey	Estimated Percent of Sample Sorted 27%
Date Processed 6/3/19	Specimens Saved 35 + 20 + 20 + 59 = 134	

D2 A2 D1 C1 Total

subsample archived in ABL until Aug 2022

