

Instructions: **Bold** fields must be completed.

Station Summary

Waterbody Name		Waterbody ID Code	Sample ID (YYYYMMDD-CY-FD) 20180718-50-2
Sampling Location RSS-R-7m-1g-071818			Database Key 164643002
SWIMS Station ID 10049350		SWIMS Station Name EMMONS CREEK - CONTROL REACH NEAR STRATTON LAKE RD	
Latitude 44.29605	Longitude -89.24131	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) WOLF RIVER		Watershed Name WAUPACA RIVER	County PORTAGE

Sample and Site Descriptors

Sample Collector (Last Name, First) DAVID A BOLHA, MICHAEL P SHUPRYT	Project Name EMMONS CREEK DISCHARGE REDUCTION MI FY18
--	---

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: Core

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min)	Estimated Area Sampled (m²)	Number of Samples in Composite	Replicate No. _____ of _____
----------------------------------	---	---------------------------------------	-------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Special Project

Water Temp. (C)	D.O. (mg/l)	D.O. (% sat.)	pH (su)	Conductivity (umhos/cm)	Transparency (cm)
------------------------	--------------------	----------------------	----------------	--------------------------------	--------------------------

Water Color	Estimated Stream Velocity (m/s)
<input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	<input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
--	--	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): _____ Gravel (ladybug to tennisball): _____
 Sand: _____ Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) _____ **Canopy Cover at Sample Site (%)** _____

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain

PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water- shed	Factors that may be influencing Water Resource Integrity	Local	Water- shed
Biological			Chemical		
Algae: - Diatoms / Periphyton			Chlorine		
- Filamentous Algae			Dissolved Oxygen		
- Planktonic Algae			Nutrients (P, N...)		
Iron Bacteria			Toxics: - Inorganic (Metals)		
Macrophytes			- Organic (PCBs, pesticides...)		
Slimes			Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion		
			Point Source - Specify:		
Physical			Pasturing of Livestock		
Bank Erosion			Runoff: - Barnyard		
Channelization: - Upstream			- Construction		
- Downstream			- Cropland		
Hydraulic Scour / Channel Incision			- Urban		
Impoundment: - Upstream			Septic Systems		
- Downstream			Tile Drainage - Organic Soils		
Low Flow			- Mineral Soils		
Sedimentation			Springs		
Sludge			Tributary(s)		
Thermal			Wetland		
Turbidity			Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter	Taxonomist <i>Dimick Jeffrey</i>	Estimated Percent of Sample Sorted
Date Processed	Specimens Saved <i>Sample archived in ABL until Sept 2022</i>	

