



**Photo #1** Dewatering area grading



**Photo #2** Dewatering area and shoreline protection



**Photo #3** Dewatering area in operation



**Photo #4** Dredge with dewatering area bank protection



**Photo #5** Dewatering area restored with silt fence



**Photo #6** Dewatering area shoreline restored with silt fence



**Photo #7** Diversion berm construction



**Photo #8** Diversion berm restored