

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name UNT to Daly		Waterbody ID Code	Sample ID (YYYYMMDD-CY-FD) 20191104-43-06
Sampling Location 10m DS of crossing			Database Key 210284829
SWIMS Station ID 10052996		SWIMS Station Name UNT TO DALY CREEK - VALLEY LINE ROAD (EAST)	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) GREEN BAY		Watershed Name LITTLE RIVER	County OCONTO

Sample and Site Descriptors

Sample Collector (Last Name, First) ANDREW HUDAK	Project Name LITTLE RIVER TWA ASSESSMENT 2018, 2019
--	---

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min)	Estimated Area Sampled (m²)	Number of Samples in Composite	Replicate No. _____ of _____
----------------------------------	---	---------------------------------------	-------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Impacted Watershed Assessment

Water Temp. (C) 5.0	D.O. (mg/l) 9.4	D.O. (% sat.) 75.8	pH (su) 7.7	Conductivity (umhos/cm) 532	Transparency (cm) 7122
-------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	----------------------------------

Water Color	Estimated Stream Velocity (m/s)
<input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	<input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 2	Average Stream Width of reach (m) 3
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): _____ Gravel (ladybug to tennisball): _____
 Sand: _____ Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 100
Canopy Cover at Sample Site (%) 100

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Isabel Dunn</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>27%</i>
Date Processed <i>1/23/2020</i>	Specimens Saved <i>Subsample archived in ABZ w/MA Apr 2023</i>	

*C3-48
 D2-49
 E1-25
 A1-20
 C2-*

