

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name NEDA CREEK		Waterbody ID Code 859100	Sample ID (YYYYMMDD-CY-FD) 20191069-14-03
Sampling Location 10 m upstream Downer Road			Database Key 212668275
SWIMS Station ID 10052329		SWIMS Station Name NEDA CREEK AT DOWNER ROAD	
Latitude 43.40337	Longitude -88.54695	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS <u>WGS84</u> or NAD83
Basin (WMU) UPPER ROCK		Watershed Name SINISSIPPI LAKE	County DODGE

Sample and Site Descriptors

Sample Collector (Last Name, First) AMRHEIN, JAMES	Project Name WILDCAT CREEK (DODGE CO) TWA 2019
--	--

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	-------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 12.2	D.O. (mg/l) 9.70	D.O. (% sat.) 91.0	pH (su)	Conductivity (umhos/cm)	Transparency (cm)
--------------------------------	----------------------------	------------------------------	----------------	--------------------------------	--------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
---	--	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): _____ Gravel (ladybug to tennisball): 70
 Sand: 30 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) N/A
Canopy Cover at Sample Site (%) 100

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter	Cough, Natalie	Taxonomist
Date Processed	2/10/20	Dimock, Jeffrey
		Estimated Percent of Sample Sorted
		33
		Specimens Saved
		Subsample archived in ABL until Jul 2023

B2-46
 A3-21
 D1
 O1
 C1
 A2
 (199)

