

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name TWIN HILL CREEK	Waterbody ID Code 89600	Sample ID (YYYYMMDD-CY-FD) 2019 0918-05-11
--	-----------------------------------	--

Sampling Location DS of Larsenville Road	Database Key 209711217
--	----------------------------------

SWIMS Station ID 10009867	SWIMS Station Name TWIN HILL CREEK - TWIN HILL CREEK AT LARSENVILLE RD
-------------------------------------	--

Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
-----------------	------------------	---	--

Basin (WMU) TWIN - DOOR - KEWAUNEE	Watershed Name WEST TWIN RIVER	County BROWN
--	--	------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) MARY GANSBERG	Project Name NE LAKESHORE TMDL SUPPLEMENTAL MONITORING 2019
---	---

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1.5	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 16.8	D.O. (mg/l) 8.1	D.O. (% sat.) 83.0	pH (su) 7.8	Conductivity (umhos/cm) 630	Transparency (cm)
--------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	--------------------------

Water Color

Clear
 Turbid
 Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s)
 Moderate (0.15 m/s - 0.5 m/s)
 Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.3	Average Stream Width of reach (m) 3
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 70 Gravel (ladybug to tennisball): 20
 Sand: _____ Clay: _____ Silt/Muck: 10 Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 20 **Canopy Cover at Sample Site (%)** 50

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Isabel Ann</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>20%</i>
Date Processed <i>11/09/2019</i>	Specimens Saved <i>Subsample archived in ABC Unit 1 Aug 2023</i>	

E2-42
 D2-65
 E3-28

