

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name BLACK CREEK		Waterbody ID Code 88300	Sample ID (YYYYMMDD-CY-FD) 20190918-36-14
Sampling Location DS CTH BB			Database Key 209711189
SWIMS Station ID 363268		SWIMS Station Name BLACK CREEK - HWY BB	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) TWIN - DOOR - KEWAUNEE		Watershed Name WEST TWIN RIVER	County MANITOWOC

Sample and Site Descriptors

Sample Collector (Last Name, First) MARY GANSBERG	Project Name NE LAKESHORE TMDL SUPPLEMENTAL MONITORING 2019
---	---

Sampling Device

D-Frame Kick Net Surber Sampler Eckman
 Ponar Artificial Substrate Hess Sampler Other: _____

Habitat Sampled

Riffle Run Pool
 Other Shoreline Composite Proportionally-Sampled Habitat
 Littoral Zone Profundal Zone Wetland

Total Sampling Time (min) 5	Estimated Area Sampled (m²) 9	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference Baseline Impact / Treatment Site
 Control Site Trend Other: _____

Water Temp. (C) 17.4	D.O. (mg/l) 9.1	D.O. (% sat.) 94.5	pH (su) 8.0	Conductivity (umhos/cm) 599	Transparency (cm) -
--------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	-------------------------------

Water Color <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input checked="" type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.3	Average Stream Width of reach (m) 10
---	---	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 60 Gravel (ladybug to tennisball): 30
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 10 **Canopy Cover at Sample Site (%)** 20

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Coash, Natalie</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>20%</i>
Date Processed <i>11/21/19</i>	Specimens Saved <i>Subsample archived in ASL unhol Aug 2023</i>	

*C3-59
 C2-37
 D1-29* } 25

