

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name POLK SPRING CREEK	Waterbody ID Code 23800	Sample ID (YYYYMMDD-CY-FD) 20191022-67-01
--	-----------------------------------	---

Sampling Location US Mayfield Rd.	Database Key 220742835
---	----------------------------------

SWIMS Station ID 10008862	SWIMS Station Name POLK SPRINGS CREEK1
-------------------------------------	--

Latitude 43.307	Longitude -88.201	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
---------------------------	-----------------------------	--	---

Basin (WMU) MILWAUKEE RIVER	Watershed Name CEDAR CREEK	County WASHINGTON
---------------------------------------	--------------------------------------	-----------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) CRAIG HELKER	Project Name MILWAUKEE RIVER BASIN AQUATIC MACROINVERTEBRATE MONITORING
--	---

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1	Number of Samples in Composite	Replicate No. _____ of _____
---------------------------------------	--	---------------------------------------	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 9.97	D.O. (mg/l) 10.69	D.O. (% sat.) 96.9	pH (su)	Conductivity (umhos/cm) 843.4	Transparency (cm) 65
--------------------------------	-----------------------------	------------------------------	----------------	---	--------------------------------

Water Color <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input checked="" type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity 2.14 circle units m/s or f/s	Average Stream Depth of reach (m) .3	Average Stream Width of reach (m) 3
--	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 70 Gravel (ladybug to tennisball): 20
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 20 **Canopy Cover at Sample Site (%)** 10

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter <i>Eric Naas</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>13%</i>
Date Processed <i>6/4/2020</i>	Specimens Saved <i>Subsample archived in ABL until Aug 2023</i>	

A2 D1
 81 84 = 105

