

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name NORTH BRANCH MILWAUKEE RIVER		Waterbody ID Code 27100	Sample ID (YYYYMMDD-CY-FD) 20191024-60-01
Sampling Location OS 505			Database Key 221307425
SWIMS Station ID 10030491	SWIMS Station Name NICHOLS CREEK - DS OF CTH N		
Latitude 43.6467	Longitude -88.0335	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS <u>WGS84</u> or NAD83
Basin (WMU) MILWAUKEE RIVER		Watershed Name NORTH BRANCH MILWAUKEE RIVER	County SHEBOYGAN

Sample and Site Descriptors

Sample Collector (Last Name, First) CRAIG HELKER	Project Name SER LONG-TERM TREND WADEABLE REFERENCE STREAM
--	--

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m²) 1	Number of Samples in Composite	Replicate No. _____ of _____
---------------------------------------	--	---------------------------------------	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 8.29	D.O. (mg/l) 11.07	D.O. (% sat.) 76.5	pH (su)	Conductivity (umhos/cm) 747.0	Transparency (cm) +120
--------------------------------	-----------------------------	------------------------------	----------------	---	----------------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	---

Measured Velocity 1.5	circle units m/s or <u>f/s</u>	Average Stream Depth of reach (m) .6	Average Stream Width of reach (m) 1.5
---------------------------------	-----------------------------------	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 50 Gravel (ladybug to tennisball): 30
 Sand: 20 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 50 **Canopy Cover at Sample Site (%)** 0

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
Physical				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

2/60

For Lab Use Only

Sample Sorter BRV	Taxonomist Dimick, Jeffrey	Estimated Percent of Sample Sorted 3.3%
Date Processed 10/24/2020	Specimens Saved Subsample archived in ASL mtdl Dec 2023	

A3^{Q3} C3^{Q1}
 99 89

(188)

