

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name UNNAMED	Waterbody ID Code 304300	Sample ID (YYYYMMDD-CY-FD) 20201015-59-04
Sampling Location		Database Key 258672030

SWIMS Station ID 10039662	SWIMS Station Name NORTH BRANCH EMBARRASS RIVER AT NORTH BRANCH ROAD
-------------------------------------	--

Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
-----------------	------------------	---	--

Basin (WMU) WOLF RIVER	Watershed Name NORTH BRANCH AND MAINSTEM EMBARRA	County SHAWANO
----------------------------------	--	--------------------------

Sample and Site Descriptors

Sample Collector (Last Name, First) ANDREW HUDAK	Project Name 2020 TWA STRASSBURG CREEK- NORTH BRANCH EMBARRA
--	--

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 3	Estimated Area Sampled (m²) 5	Number of Samples in Composite 1	Replicate No. 1 of 1
---------------------------------------	--	--	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: TWA

Water Temp. (C) 6.7	D.O. (mg/l) 7.22	D.O. (% sat.) 59	pH (su)	Conductivity (umhos/cm) 197	Transparency (cm) 2122
-------------------------------	----------------------------	----------------------------	----------------	---------------------------------------	----------------------------------

Water Color

Clear
 Turbid
 Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s)
 Moderate (0.15 m/s - 0.5 m/s)
 Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.2	Average Stream Width of reach (m) 2.0
--	---	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): 10 Rubble (tennisball to basketball): 30 Gravel (ladybug to tennisball): 30
 Sand: 20 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: 10 Coarse Woody Debris: _____ Other (): _____

Embeddedness of Substrate at Sample Site (%) 20 **Canopy Cover at Sample Site (%)** 100

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water-shed	Factors that may be influencing Water Resource Integrity	Local	Water-shed
Biological			Chemical		
Algae: - Diatoms / Periphyton	N	N	Chlorine	N	N
- Filamentous Algae	N	N	Dissolved Oxygen	N	N
- Planktonic Algae	N	N	Nutrients (P, N...)	N	U
Iron Bacteria	N	N	Toxics: - Inorganic (Metals)	N	N
Macrophytes	N	N	- Organic (PCBs, pesticides...)	N	U
Slimes	N	N	Other - Specify:		
Other - Specify:	N	N	Sources of Stream Impacts		
			Bank Erosion	N	N
			Point Source - Specify:	N	N
Physical			Pasturing of Livestock	N	U
Bank Erosion	N	N	Runoff: - Barnyard	N	U
Channelization: - Upstream	N	N	- Construction	N	N
- Downstream	N	N	- Cropland	N	U
Hydraulic Scour / Channel Incision	N	N	- Urban	N	N
Impoundment: - Upstream	N	N	Septic Systems	N	U
- Downstream	N	N	Tile Drainage - Organic Soils	N	U
Low Flow	U	U	- Mineral Soils	N	U
Sedimentation	N	N	Springs	U	U
Sludge	N	N	Tributary(s)	U	U
Thermal	N	N	Wetland	U	U
Turbidity	N	N	Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter Dunn, Isabel	Taxonomist Dimick, Jeffrey	Estimated Percent of Sample Sorted 14.1%
Date Processed 8/16/2021	Specimens Saved Subsample archived in ABC until Oct 2022	

4:00-7:00

D3 B3 A4
 1-11
 1-31
 2-27
 3-28
 4-4

(128)

