

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name TOAD CREEK		Waterbody ID Code 317600	Sample ID (YYYYMMDD-CY-FD) 20210923-45-04
Sampling Location Townhall Rd		Database Key 293164311	
SWIMS Station ID 10054811		SWIMS Station Name TOAD CREEK DS OF TOWN HALL RD	
Latitude 44.55849	Longitude -88.41372	Lat/Long Determination Method (circle) SWIMS <u>SWDV</u> GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) WOLF RIVER		Watershed Name SHIOC RIVER	County OUTAGAMIE

Sample and Site Descriptors	
Sample Collector (Last Name, First) ANDREW HUDAK	Project Name TOAD CREEK- TWA

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 4	Estimated Area Sampled (m ²) 7	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>1</u>
--------------------------------	---	-------------------------------------	------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Targeted Watershed Assessment

Water Temp. (C) 12.78	D.O. (mg/l) 11.06	D.O. (% sat.) 102.7	pH (su) 7.91	Conductivity (umhos/cm) .919	Transparency (cm) 7122
--------------------------	----------------------	------------------------	-----------------	---------------------------------	---------------------------

Water Color

Clear
 Turbid
 Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s)
 Moderate (0.15 m/s - 0.5 m/s)
 Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
---	-----------------------------------	-----------------------------------

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 20 Gravel (ladybug to tennisball): 40
 Sand: 30 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: 10 Coarse Woody Debris: _____ Other (_____): _____
 Embeddedness of Substrate at Sample Site (%) 30 Canopy Cover at Sample Site (%) 50

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Physical				Runoff: - Barnyard			
Bank Erosion				- Construction			
Channelization: - Upstream				- Cropland			
- Downstream				- Urban			
Hydraulic Scour / Channel Incision				Septic Systems			
Impoundment: - Upstream				Tile Drainage - Organic Soils			
- Downstream				- Mineral Soils			
Low Flow				Springs			
Sedimentation				Tributary(s)			
Sludge				Wetland			
Thermal				Other - Specify:			
Turbidity							
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Katherine McClure</i>	Taxonomist <i>Dimrek Jeffrey</i>	Estimated Percent of Sample Sorted <i>4.7%</i>
Date Processed <i>7/2/2022</i>	Specimens Saved <i>Subsample archived in ABC until Sept 2025</i>	

*C393:20 B292:83
 C394:32 B293:
 C391: B294:
 C392: B291:*

148

